BLUEBOOK CA Property Condition & Inspection





123 Main Street Lake Forest CA 92630

MLS#: 13606148 Bedrooms:4 Baths:2.1 Year Built:1999 Total Living Area:1,988 SF Property Type:Single Family Detached Bluebook ID#: 11201 Inspection Date: 12/6/2013 Date Printed: 1/9/2014 9:50:20 PM (UTC)

Repair Summary

Subject Proper	ty				
Bathroom:	\$0.00	Bedroom:	\$190.62	Deck:	\$0.00
Dining Room:	\$44.08	Exterior Grounds:	\$0.00	Family Room:	\$66.50
Garage:	\$0.00	Half Bath:	\$0.00	Kitchen:	\$489.30
Laundry:	\$0.00	Living Room:	\$66.50	Main Structure:	\$170.48
Systems:	\$5,222.29				
				Es	timated Total Repairs: \$6,249,77

LR =Lender Required CR =Cosmetic Repair ER =Emergency Repair IS =Initial Secure CL =Claims Recovery RE =Repair RV =Renovation RR =Repair Recommended RN =Repair Not Recommended

123 Main Street Lake Forest CA 92630

Bathroom					
Description	QTY UOM	Condition	Quality	Age	Status
Counter Tops: Laminate		Fair	Basic	11 to 15 Years	Functional / Acceptable As Is
Flooring & Steps: Vinyl		Fair	Basic	11 to 15 Years	Functional / Acceptable As Is
General Items: Walls & Railings		Fair	Basic	11 to 15 Years	Functional / Acceptable As Is
General Items: Ceilings		Fair	Basic	11 to 15 Years	Functional / Acceptable As Is
General Items: Lighting & Electrical		Fair	Basic	11 to 15 Years	Functional / Acceptable As Is
General Items: Doors		Fair	Basic	11 to 15 Years	Functional / Acceptable As Is
General Items: Windows		Fair	Basic	11 to 15 Years	Functional / Acceptable As Is
Bathroom Items: Toilets		Fair	Basic	11 to 15 Years	Functional / Acceptable As Is
Bathroom Items: Bathroom Sink(s)		Fair	Basic	11 to 15 Years	Functional / Acceptable As Is
Bathroom Items: Faucets & Fixtures		Fair	Basic	11 to 15 Years	Functional / Acceptable As Is
Bathroom Items: Cabinets & Shelves		Fair	Basic	11 to 15 Years	Functional / Acceptable As Is
Showers & Tubs: Shower Tub Combo		Fair	Basic	11 to 15 Years	Functional / Acceptable As Is

Estimated Bathroom Repairs: \$0.00

Bathroom 2							
Description		QTY	UOM	Condition	Quality	Age	Status
Counter Tops: Lami	nate			Good	Basic	11 to 15 Years	Functional / Acceptable As Is
Flooring & Steps: Vi	nyl			Good	Basic	11 to 15 Years	Functional / Acceptable As Is
General Items: Wall	s & Railings			Good	Basic	11 to 15 Years	Functional / Acceptable As Is
General Items: Ceili	ngs			Good	Basic	11 to 15 Years	Functional / Acceptable As Is

General Items: Lighting & Electrical	Good	Basic	11 to 15 Years	Functional / Acceptable As Is
General Items: Doors	Good	Basic	11 to 15 Years	Functional / Acceptable As Is
General Items: Windows	Good	Basic	11 to 15 Years	Functional / Acceptable As Is
Bathroom Items: Toilets	Good	Basic	11 to 15 Years	Functional / Acceptable As Is
Bathroom Items: Bathroom Sink(s)	Good	Basic	11 to 15 Years	Functional / Acceptable As Is
Bathroom Items: Faucets & Fixtures	Good	Basic	11 to 15 Years	Functional / Acceptable As Is
Bathroom Items: Cabinets & Shelves	Good	Basic	11 to 15 Years	Functional / Acceptable As Is
Showers & Tubs: Separate Tub	Good	Basic	11 to 15 Years	Functional / Acceptable As Is
Showers & Tubs: Separate Shower	Good	Basic	11 to 15 Years	Functional / Acceptable As Is

Estimated Bathroom Repairs: \$0.00

Bedroom									
Description	QTY	UOM	Condition	Quality	Age		Status		
Flooring & Steps: Carpet			Fair	Basic	11 to 1	15 Years	Needs	Repair/Replace	e/Cleaning
Repair Description Clean Carpet - Heavily Soiled					QTY 175.00	UM SF	Price \$0.38	Total \$66.50	Repair Code CR,RR,RE
General Items: Walls & Railings			Good	Basic	11 to 1	15 Years	Functio	nal / Acceptable	e As Is
General Items: Ceilings			Good	Basic	11 to 1	15 Years	Functio	nal / Acceptable	e As Is
General Items: Lighting & Electrical			Good	Basic	11 to 1	15 Years	Functio	nal / Acceptable	e As Is
General Items: Doors			Good	Basic	11 to 1	15 Years	Functio	nal / Acceptable	e As Is
General Items: Windows			Good	Basic	11 to 1	15 Years	Functio	nal / Acceptable	e As Is
							E	stimated Bedro	oom Repairs: \$66.50

Bedroom 2

Bedroom 2									
Description	QTY	UOM	Condition	Quality	Age		Status		
Flooring & Steps: Carpet			Poor	Basic	11 to 1	15 Years	Needs	Repair/Replace	e/Cleaning
Repair Description Clean Carpet - Steam Clean					QTY 116.00	UM SF	Price \$0.31	Total \$35.96	Repair Code CR,RR,RE
General Items: Walls & Railings			Good	Basic	11 to 1	15 Years	Functio	nal / Acceptable	e As Is
General Items: Ceilings			Good	Basic	11 to 1	15 Years	Functio	nal / Acceptable	e As Is
General Items: Lighting & Electrical			Good	Basic	11 to 1	15 Years	Functio	nal / Acceptable	e As Is
General Items: Doors			Good	Basic	11 to 1	15 Years	Functio	nal / Acceptable	e As Is
General Items: Windows			Good	Basic	11 to 1	15 Years	Functio	nal / Acceptable	e As Is
							E	stimated Bedro	oom Repairs: \$35.96

Bedroom 3									
Description	QTY	UOM	Condition	Quality	Age		Status		
Flooring & Steps: Carpet			Poor	Basic	11 to	15 Years	Needs	Repair/Replace	e/Cleaning
Repair Description					QTY	UM	Price	Total	Repair Code
Clean Carpet - Heavily Soiled					116.00	SF	\$0.38	\$44.08	CR,RR,RE
General Items: Walls & Railings			Good	Basic	11 to 1	15 Years	Functio	nal / Acceptable	e As Is

General Items: Ceilings	Good	Basic	11 to 15 Years	Functional / Acceptable As Is
General Items: Lighting & Electrical	Good	Basic	11 to 15 Years	Functional / Acceptable As Is
General Items: Doors	Good	Basic	11 to 15 Years	Functional / Acceptable As Is
General Items: Windows	Good	Basic	11 to 15 Years	Functional / Acceptable As Is

Estimated Bedroom Repairs: \$44.08

Bedroom 4

Status
ars Needs Repair/Replace/Cleaning
Price Total Repair Code \$0.38 \$44.08 CR,RR,RE
ars Functional / Acceptable As Is
Functional / Acceptable As Is
Functional / Acceptable As Is
Functional / Acceptable As Is
ars Functional / Acceptable As Is
3

Deck						
Description	QTY	UOM	Condition	Quality	Age	Status
Flooring: Decking			Good	Basic	11 to 15 Years	Functional / Acceptable As Is
General Items: Lighting & Electrical			Good	Basic	11 to 15 Years	Functional / Acceptable As Is
General Items: Stairs, Steps & Railings			Good	Basic	11 to 15 Years	Functional / Acceptable As Is
						Estimated Deck Renairs: \$0.00

Estimated Deck Repairs: \$0.00

Dining Room								
Description	QTY UOM	Condition	Quality	Age		Status		
Flooring & Steps: Carpet		Poor	Basic	11 to 7	15 Years	Needs	Repair/Replace	e/Cleaning
Repair Description Clean Carpet - Heavily Soiled				QTY 116.00	UM SF	Price \$0.38	Total \$44.08	Repair Code CR,RR,RE
General Items: Walls & Railings		Good	Basic	11 to ²	15 Years	Functio	nal / Acceptable	e As Is
General Items: Ceilings		Good	Basic	11 to ⁻	15 Years	Functio	nal / Acceptable	e As Is
General Items: Lighting & Electrical		Good	Basic	11 to ⁻	15 Years	Functio	nal / Acceptable	e As Is
General Items: Doors		Good	Basic	11 to ⁻	15 Years	Functio	nal / Acceptable	e As Is
General Items: Windows		Good	Basic	11 to ⁻	15 Years	Functio	nal / Acceptable	e As Is
						Estin	nated Dining Re	oom Repairs: \$44.08

Exterior Grounds						
Description	QTY	UOM	Condition	Quality	Age	Status
Driveways: Concrete			Good	Basic	11 to 15 Years	Functional / Acceptable As Is

Walkways: Concrete	Good	Basic	11 to 15 Years	Functional / Acceptable As Is
General Items: Landscape	Good	Basic	11 to 15 Years	Functional / Acceptable As Is
General Items: Fences & Gates	Good	Basic	11 to 15 Years	Functional / Acceptable As Is
General Items: Lighting & Electrical	Good	Basic	11 to 15 Years	Functional / Acceptable As Is
General Items: Stairs, Steps & Railings	Good	Basic	11 to 15 Years	Functional / Acceptable As Is

Estimated Exterior Grounds Repairs: \$0.00

Family Room

Description QTY UOM Condition Quality Age Status Flooring & Steps: Carpet Poor Basic 11 to 15 Years Needs Repair/Replace/Cleaning Repair Description Clean Carpet - Heavily Soiled V V V V V Repair Code CR,RR,RE General Items: Walls & Railings Image: Code CR,RR,RE Good Basic 11 to 15 Years Functional / Acceptable As Is General Items: Lighting & Electrical Image: Code CR, Code CR, Code CR, Code CR, Code CR, Code CR,	r anny Room								
QTY UM Price Total Repair Code Clean Carpet - Heavily Soiled Good Basic 11 to 15 Years Functional / Acceptable As Is General Items: Walls & Railings Good Basic 11 to 15 Years Functional / Acceptable As Is General Items: Lighting & Electrical Good Basic 11 to 15 Years Functional / Acceptable As Is General Items: Doors Good Basic 11 to 15 Years Functional / Acceptable As Is General Items: Windows Good Basic 11 to 15 Years Functional / Acceptable As Is	Description	QTY	UOM	Condition	Quality	Age	Status		
Repair Description Clean Carpet - Heavily SoiledOTY 175.00UM SFPrice \$0.38Total \$66.50Repair Code CR,RR,REGeneral Items: Walls & RailingsGoodBasic11 to 15 YearsFunctional / Acceptable As IsGeneral Items: CeilingsGoodBasic11 to 15 YearsFunctional / Acceptable As IsGeneral Items: Lighting & ElectricalGoodBasic11 to 15 YearsFunctional / Acceptable As IsGeneral Items: DoorsGoodBasic11 to 15 YearsFunctional / Acceptable As IsGeneral Items: WindowsGoodBasic11 to 15 YearsFunctional / Acceptable As Is	Flooring & Steps: Carpet			Poor	Basic	11 to 15 Years	Needs Repair/Replace/Cleaning		
General Items: CeilingsGoodBasic11 to 15 YearsFunctional / Acceptable As IsGeneral Items: Lighting & ElectricalGoodBasic11 to 15 YearsFunctional / Acceptable As IsGeneral Items: DoorsGoodBasic11 to 15 YearsFunctional / Acceptable As IsGeneral Items: WindowsGoodBasic11 to 15 YearsFunctional / Acceptable As Is	Repair Description						· · · · · ·		
General Items: Lighting & ElectricalGoodBasic11 to 15 YearsFunctional / Acceptable As IsGeneral Items: DoorsGoodBasic11 to 15 YearsFunctional / Acceptable As IsGeneral Items: WindowsGoodBasic11 to 15 YearsFunctional / Acceptable As Is	General Items: Walls & Railings			Good	Basic	11 to 15 Years	Functional / Acceptable As Is		
General Items: Doors Good Basic 11 to 15 Years Functional / Acceptable As Is General Items: Windows Good Basic 11 to 15 Years Functional / Acceptable As Is	General Items: Ceilings			Good	Basic	11 to 15 Years	Functional / Acceptable As Is		
General Items: Windows Good Basic 11 to 15 Years Functional / Acceptable As Is	General Items: Lighting & Electrical			Good	Basic	11 to 15 Years	Functional / Acceptable As Is		
	General Items: Doors			Good	Basic	11 to 15 Years	Functional / Acceptable As Is		
Estimated Family Room Repairs: \$66.5	General Items: Windows			Good	Basic	11 to 15 Years	Functional / Acceptable As Is		
							Estimated Family Room Repairs: \$6		

Garage						
Description	QTY	UOM	Condition	Quality	Age	Status
Garage Doors: Double Car Door			Good	Basic	11 to 15 Years	Functional / Acceptable As Is
General Items: Walls & Railings			Good	Basic	11 to 15 Years	Functional / Acceptable As Is
General Items: Ceilings			Good	Basic	11 to 15 Years	Functional / Acceptable As Is
General Items: Lighting & Electrical			Good	Basic	11 to 15 Years	Functional / Acceptable As Is
General Items: Doors			Good	Basic	11 to 15 Years	Functional / Acceptable As Is
Flooring & Steps: Concrete			Good	Basic	11 to 15 Years	Functional / Acceptable As Is
						Estimated Garage Repairs: \$0.00

Half Bath						
Description	QTY	UOM	Condition	Quality	Age	Status
Counter Tops: Laminate			Good	Basic	11 to 15 Years	Functional / Acceptable As Is
Flooring & Steps: Vinyl			Good	Basic	11 to 15 Years	Functional / Acceptable As Is
General Items: Walls & Railings			Good	Basic	11 to 15 Years	Functional / Acceptable As Is
General Items: Ceilings			Good	Basic	11 to 15 Years	Functional / Acceptable As Is
General Items: Lighting & Electrical			Good	Basic	11 to 15 Years	Functional / Acceptable As Is
General Items: Doors			Good	Basic	11 to 15 Years	Functional / Acceptable As Is
General Items: Windows			Good	Basic	11 to 15 Years	Functional / Acceptable As Is
Bathroom Items: Toilets			Good	Basic	11 to 15 Years	Functional / Acceptable As Is
Bathroom Items: Bathroom Sink(s)			Good	Basic	11 to 15 Years	Functional / Acceptable As Is
Bathroom Items: Faucets & Fixtures			Good	Basic	11 to 15 Years	Functional / Acceptable As Is
Bathroom Items: Cabinets & Shelves			Good	Basic	11 to 15 Years	Functional / Acceptable As Is

Kitchen									
Description	QTY	UOM	Condition	Quality	Age		Status		
Flooring & Steps: Vinyl			Poor	Basic	11 to 1	15 Years	Needs	Repair/Replace	e/Cleaning
Repair Description Remove Discolored Vinyl Floor Sheet - I Replacement or Haul Away) Replace Vinyl Floor - Sheet - Good	Remove, Tre	at Subfloor	, Seal (Does r	not include	QTY 105.00 105.00	UM SF SF	Price \$2.09 \$2.57	Total \$219.45 \$269.85	Repair Code CR,RR,RE CR,RR,RE
Appliances: Dishwashers			Good	Basic	11 to 1	15 Years	Functio	nal / Acceptable	e As Is
Appliances: Refrigerators			Good	Basic	11 to 1	15 Years	Functio	nal / Acceptable	e As Is
Appliances: Built-In Microwave			N/A	N/A	N/A		N/A		
Appliances: Range Hoods			N/A	N/A	N/A		N/A		
Appliances: Range/Stove			N/A	N/A	N/A		N/A		
Appliances: Cook Tops			Good	Basic	11 to 1	15 Years	Functio	nal / Acceptable	e As Is
Appliances: Wall Ovens			Good	Basic	11 to 1	15 Years	Functional / Acceptable As Is		
Plumbing: Garbage Disposals			Good	Basic	11 to 1	15 Years	Functio	nal / Acceptable	e As Is
Plumbing: Kitchen Sinks & Faucets			Good	Basic	11 to 1	15 Years	Functio	nal / Acceptable	e As Is
Cabinets & Shelves: Kitchen Cabinets Shelves	&		Good	Basic	11 to 1	15 Years	Functio	nal / Acceptable	e As Is
Counter Tops: Tile - Ceramic			Good	Basic	11 to 1	15 Years	Functio	nal / Acceptable	e As Is
Island Cabinets & Shelves: Island Cabi & Shelves	nets		Good	Basic	11 to 1	15 Years	Functio	nal / Acceptable	e As Is
Island Counter Tops: Tile - Ceramic			Good	Basic	11 to 1	15 Years	Functio	nal / Acceptable	e As Is
General Items: Walls & Railings			Good	Basic	11 to 1	15 Years	Functio	nal / Acceptable	e As Is
General Items: Ceilings			Good	Basic	11 to 1	15 Years	Functio	nal / Acceptable	e As Is
General Items: Lighting & Electrical			Good	Basic	11 to 1	15 Years	Functio	nal / Acceptable	e As Is
General Items: Doors			Good	Basic	11 to 1	15 Years	Functio	nal / Acceptable	e As Is
General Items: Windows			Good	Basic	11 to 1	15 Years	Functio	nal / Acceptable	e As Is
							E	stimated Kitch	en Repairs: \$489.30

Laundry						
Description	QTY	UOM	Condition	Quality	Age	Status
Flooring & Steps: Vinyl			Good	Basic	11 to 15 Years	Functional / Acceptable As Is
General Items: Walls & Railings			Good	Basic	11 to 15 Years	Functional / Acceptable As Is
General Items: Ceilings			Good	Basic	11 to 15 Years	Functional / Acceptable As Is
General Items: Lighting & Electrical			Good	Basic	11 to 15 Years	Functional / Acceptable As Is
General Items: Doors			Good	Basic	11 to 15 Years	Functional / Acceptable As Is
General Items: Windows			Good	Basic	11 to 15 Years	Functional / Acceptable As Is
Laundry Items: Cabinets & Shelves			Good	Basic	11 to 15 Years	Functional / Acceptable As Is
Laundry Items: Counter Tops			Good	Basic	11 to 15 Years	Functional / Acceptable As Is
						Estimated Laundry Popairs: \$0.00

Estimated Laundry Repairs: \$0.00

Description	QTY	UOM	Condition	Quality	Age	Status
Flooring & Steps: Carpet			Poor	Basic	11 to 15 Years	Needs Repair/Replace/Cleaning
Repair Description Clean Carpet - Heavily Soiled					QTY UM 175.00 SF	Price Total Repair Code \$0.38 \$66.50 CR,RR,RE
General Items: Walls & Railings			Fair	Basic	11 to 15 Years	Functional / Acceptable As Is
General Items: Ceilings			Fair	Basic	11 to 15 Years	Functional / Acceptable As Is
General Items: Lighting & Electrical			Fair	Basic	11 to 15 Years	Functional / Acceptable As Is
General Items: Doors			Fair	Basic	11 to 15 Years	Functional / Acceptable As Is
General Items: Windows			Fair	Basic	11 to 15 Years	Functional / Acceptable As Is

Estimated Living Room Repairs: \$66.50

Main Structure									
Description	QTY	UOM	Condition	Quality	Age		Status		
Exterior Walls: Wood			Fair	Basic	11 to	15 Years	Needs R	epair/Replace	e/Cleaning
Repair Description Paint Exterior Walls - 1 Story - 1 Coat - Min charge up to 100 SF Repair Siding - Wood - up to 20 S.F.					QTY 1.00 1.00	UM M/C M/C	Price \$59.04 \$111.44	Total \$59.04 \$111.44	Repair Code LR,RR,RE LR,RR,RE
Roofing: Asphalt Shingles			Fair	Basic	11 to	15 Years Functional / Acceptable As Is			e As Is
Foundations: Raised/Crawl Space			Good	Basic	11 to	15 Years	Function	al / Acceptable	e As Is
General Items: Chimneys			Good	Basic	11 to	15 Years	Function	al / Acceptable	e As Is
General Items: Stairs, Steps & Railings		Good	Basic	11 to 15 Years		Functional / Acceptable As Is		e As Is	
General Items: Lighting & Electrical			Good	Basic	11 to	15 Years	ars Functional / Acceptable As Is		
							Estimated	I Main Structu	re Repairs: \$170.48

Systems								
Description	QTY UOM	Condition	Quality	Age		Status		
Cooling: Central A/C		N/A	N/A	N/A		N/A		
Repair Description Replace Central Air Conditioner Unit -	13 SEER - 3 Ton			QTY 1.00	UM EA	Price \$2,929.59	Total \$2,929.59	Repair Code CR,RR,RE
Plumbing - Interior: Water Heater		Good	Basic	11 to	15 Years	Functiona	I / Acceptable	As Is
Plumbing - Exterior: Septic Tanks		N/A	N/A	N/A		N/A		
Plumbing - Exterior: Wells		N/A	N/A	N/A		N/A		
Heating: Forced Air		N/A	N/A	N/A		N/A		
Repair Description Replace Forced Air - Gas Furnace - 80	% Efficiency - Single/T	wo Stage - 90,00	0 BTU	QTY 1.00	UM EA	Price \$2,292.70	Total \$2,292.70	Repair Code LR,RR,RE
Electrical: Electrical Panel		Good	Basic	11 to	15 Years	Functiona	I / Acceptable	As Is
						Estima	ited Systems	Repairs: \$5,222.29











Area:Bedroom 3 Repair For: Flooring & Steps -Carpet









Area:Systems Repair For: Cooling -Central A/C





Area:Kitchen Repair For: Flooring & Steps -Vinyl

Area:Systems **Repair For: Heating -Forced Air**





Area:Dining Room Repair For: Flooring & Steps -Carpet

Area:Family Room Repair For: Flooring & Steps -Carpet



Area:Living Room Repair For: Flooring & Steps -Carpet



Copyright © 2014 Bluebook International - All Rights Reserved

DISCLAIMER: This report is subject to Bluebook's Terms & Conditions, Users License, and Privacy Policy, and any applicable contract terms which you agreed to as a condition of accessing Bluebook's systems. All information, how ever derived, entered or implemented including all data contained herein, is the sole property of the Bluebook and its third party providers. Your use constitutes a license. This report and the data contained in it may not be re-sold, remarketed, syndicated, compiled, or published without prior written permission from Bluebook. II This report (including graphs, charts, and photos) is derived from the use of proprietary automated valuation technologies (including mathematical and statistical modeling), public record data, economic and other data, your inputs, and other proprietary predictive technologies to provide an estimate of estimated values and costs associated or related to the property. II This report does not constitute an appraisal or similar valuation and may not be relied upon as such. Inputs do not necessarily include visual inspections, neighborhood characteristics, school zones, topography, and other factors that may influence value. II THIS REPORT IS AN OPINION THAT MAY BE INACCURATE AND IS PROVIDED SOLELY AS AN INFORWATIONAL TOOL NOT DESIGNED TO PROVIDE DEFINITIVE ANSWERS. ALL ELEMENTS ARE OFFERED "AS IS" AND BLUEBOOK EXPRESSLY DISCLAIMS ANY AND ALL WARRANTIES, REPRESENTATIONS, AND GUARANTEES OF ANY NATURE, EXPRESS, IMPLIED OR OTHERWISE, INCLUDING BUT NOT LIMITED TO ANY IMPLIED WARRANTIES OF MERCHANTABLITILY, NONINFRINGEMENT, TITLE, QUIET ENJOYMENT, ACCURACY, OR FITNESS FOR A PARTICULAR PURPOSE. IN NO EVENT SHALL BLUEBOOK (OR ITS SUPPLIERS) BE LIABLE FOR ANY GENERAL, DIRECT, SPECIAL, INCIDENTAL, INDIRECT OR CONSEQUENTIAL DAMAGES OF ANY KIND, OR ANY DAMAGES WHATSOEVER (INCLUDING WITHOUT LIMITATION, THOSE RESULTING FROM USE OF THE PRODUCT, INCLUDING : (1) RELIANCE ON THE MATERIALS PRESENTED, (2) COSTS OF REPLACEMENT GOODS, (3) LOSS OF USE, DATA OR PROFITS, (4) DELAYS OR BUSI